

消防處
牌照及審批總區
香港九龍尖沙咀東康莊道1號5樓
消防總部大廈



**FIRE SERVICES DEPARTMENT
LICENSING AND CERTIFICATION
COMMAND**

FIRE SERVICES HEADQUARTERS BUILDING,
No.1 Hong Chong Road, 5/F,
Tsim Sha Tsui East Kowloon,
Hong Kong.

本處檔號 OUR REF.: (27) in FP 207/0018 II

來函檔號 YOUR REF

電報掛號 TELEX:39607 HKFSD HX

圖文傳真 FAX: 852-2367-3631

電子郵件 E-mail lcpolic2@hkfsd.gov.hk

電話 TEL NO.: 2733 7744

2 January 2003

Fivalco Limited
Manasty Road, Peterborough
Cambridgeshire PE2 6UP
United Kingdom.

Dear Mr. Alan Stimpson,

Acceptance of Flexible Sprinkler Connections

I refer to my interim reply of 11.12.2002 on the captioned subject.

The proposed use of the following flexible sprinkler connections, which were certificated by Building Research Establishment Ltd (BRE), is acceptable to this Department:-

Manufacturer : Dong A Flexible Metal Tubes Company Limited, Gyung Gi-Do, Korea
Type : Type 2 Bendable hoses
Testing Standard : LPS 1261:Issue 1
Supporting Document : Test Report 206538 issued by Building Research Establishment Ltd. (BRE) in February 2002.

Model	Length (mm)	Nominal Size / Connection		Max. Working Pressure (bar)	LPCB Ref. No.
		Supply	Outlet		
Rapidrop® SP-1A	780	R1 external thread (1" BSPT)	Rc1/2 internal thread (1/2" BSPT)	16	566a/01
Rapidrop® SP-2A	1220				
Rapidrop® SP-3A	1540				
Rapidrop® SP-4A	1880				
Rapidrop® SP-5A	2540				
Rapidrop® SP-6A	3220				


.../P.2

Model	Length (mm)	Nominal Size / Connection		Max. Working Pressure (bar)	LPCB Ref. No.
		Supply	Outlet		
Rapidrop® SP-1B	780	R1 external thread (1" BSPT)	Rc3/4 internal thread (3/4" BSPT)	16	566a/01
Rapidrop® SP-2B	1220				
Rapidrop® SP-3B	1540				
Rapidrop® SP-4B	1880				
Rapidrop® SP-5B	2540				
Rapidrop® SP-6B	3220				
Rapidrop® SP-1C	780	R1 external thread (1" BSPT)	R1 internal thread (1" BSPT)	16	566a/01
Rapidrop® SP-2C	1220				
Rapidrop® SP-3C	1540				
Rapidrop® SP-4C	1880				
Rapidrop® SP-5C	2540				
Rapidrop® SP-6C	3220				
Rapidrop® SPN-1A	780	R1 external thread (1" BSPT)	Rc1/2 internal thread (1/2" BSPT)	16	566a/02
Rapidrop® SPN-2A	1220				
Rapidrop® SPN-3A	1540				
Rapidrop® SPN-4A	1880				
Rapidrop® SPN-5A	2540				
Rapidrop® SPN-6A	3220				
Rapidrop® SPN-1B	780	R1 external thread (1" BSPT)	Rc3/4 internal thread (3/4" BSPT)	16	566a/02
Rapidrop® SPN-2B	1220				
Rapidrop® SPN-3B	1540				
Rapidrop® SPN-4B	1880				
Rapidrop® SPN-5B	2540				
Rapidrop® SPN-6B	3220				
Rapidrop® SPW-1A	780	R1 external thread (1" BSPT)	Rc1/2 internal thread (1/2" BSPT)	16	566a/03
Rapidrop® SPW-2A	1220				
Rapidrop® SPW-3A	1540				
Rapidrop® SPW-4A	1880				
Rapidrop® SPW-5A	2540				
Rapidrop® SPW-6A	3220				
Rapidrop® SPW-1B	780	R1 external thread (1" BSPT)	Rc3/4 internal thread (3/4" BSPT)	16	566a/03
Rapidrop® SPW-2B	1220				
Rapidrop® SPW-3B	1540				
Rapidrop® SPW-4B	1880				
Rapidrop® SPW-5B	2540				
Rapidrop® SPW-6B	3220				

Please note that the above acceptance is subject to :-

- i. all conditions stipulated in the above-mentioned test report being complied with; and
- ii. the installation conforming to FSD Circular Letter No. 2/94 Rules for Automatic Sprinkler Installations.

Yours faithfully,

A handwritten signature in black ink, consisting of a series of loops and a long horizontal stroke, positioned above the printed name.

(LAU Kwai-shan)

for Director of Fire Services

LKS/RL/lkc